Update-Description

inLab CAD SW 19.1
- Partial Framework

This document describes changes and improvements compared to the previous version inLab CAD SW 19.0 Partial Framework.

August 2019

Dentsply
Sirona

General:

Fixed bug with STL export

Depending on the case, STL Export sometimes had a very long waiting time. This behavior has been corrected.

Create base plates with patterns

The creation of base plates with patterns could lead to software crashes in some cases. This behavior has been corrected.

Quality improvement and stability

Dentsply Sirona continuously improves the quality of its products. As part of this release, several improvements have been made and known software bugs have been fixed. We always recommend using the latest software version.